Comprehensive Asbestos Survey

Residential Structure 113 League Street Easley, South Carolina 29640 September 8, 2025

> Prepared for: Mr. Tor Ellstrom The City of Easley

> > Prepared by:



UPSTATE ENVIRONMENTAL

194 Evans Road Easley, South Carolina 29640 (864) 884-4284

Comprehensive Asbestos Survey Upstate Environmental, LLC

Foreword

This pre-demolition comprehensive asbestos survey has been prepared by Upstate Environmental LLC (Upstate) of Easley, South Carolina for the residential structure located at 113 League Street in Easley, South Carolina. Demolition by a contractor is being considered, so it is subject to inspection and abatement (if necessary) by the requirements of the South Carolina Department of Environmental Services (SCDES) regulation R.61-86.1.

This survey has been done at the request of Mr. Tor Ellstrom of The City of Easley. It has been prepared for Mr. Ellstrom and is intended for their expressed purposes only. This survey should not be relied upon or made use of by any party other than the aforementioned. Any questions or comments concerning this survey should be directed to Johnny Satterfield at the offices of Upstate Environmental LLC located at 194 Evans Road, Easley, South Carolina 29640 or 864-884-4284.

Executive Summary

Mr. Tor Ellstrom of The City of Easley retained Upstate to perform a comprehensive asbestos survey for the residential structure located at 113 League Street in Easley, South Carolina.

On August 27, 2025, Johnny Satterfield performed the site survey. During this time, asbestos bulk samples were collected of suspect asbestos containing materials throughout the subject property that were readily accessible. A total of nineteen (19) bulk samples from five (5) homogeneous areas were collected at the subject property for polarized light microscopy (PLM) and transmission electron microscopy (TEM) analysis.

The analytical results indicate **the following** sampled suspect asbestos materials sampled tested **POSTIVE** for asbestos containing over 1%.

Homogeneous area "A"- Exterior cementitious siding. 15% Chrysotile. Approximately 3500 Square Feet Homogeneous area "B"- Drywall and joint compound throughout. 2-3% Chrysotile. Approximately 4550 Square Feet

Johnny fatherline

Signature

I hereby attest that the information contained herein is true, accurate, and complete to the best of my ability. This report has been prepared by the undersigned.

Date: 9-8-2025

Johnny Satterfield

SCDES Asbestos Building Inspector (License BI-01674)

Upstate Environmental, LLC

Table of Contents

113 League Street Residential Structure in Easley, South Carolina

<u>Section</u>

1.0 INTRODUCTION
2.0 SAMPLE COLLECTION PROCEDURES
3.0 LABORATORY ANALYSIS METHODS
4.0 STATE ASBESTOS REGULATIONS
5.0 DESCRIPTION OF BUILDING
6.0 SUMMARY OF RESULTS
7.0 CONCLUSIONS AND RECOMMENDATIONS

Appendix A – Photographs of survey site

Appendix B – Laboratory Analysis

Appendix C – Inspector credentials

Section 1.0 - Introduction

This comprehensive asbestos survey has been conducted for the residential structure located at 113 League Street located in Easley, South Carolina. Samples of suspect asbestos containing materials (ACM) were collected from the building on August 27, 2025. Johnny Satterfield of Upstate conducted the property walk through and survey. The purpose of this survey was to identify the presence of ACM's and determine the physical condition (friability) and potential disturbance of positive materials. The building is scheduled for demolition.

Asbestos is a general name for a group of silicate minerals, which have the form of crystalline fibers. These materials resist fire and attack by chemicals, fungi, and bacteria. Asbestos was widely used before 1978 as a major component in fireproofing, pipe insulation, flooring, and roofing materials. It was also commonly used as reinforcement in plaster, gypsum board, floor tile, and cements (tile and roofing).

The Environmental Protection Agency (EPA) has not accepted any exposure to asbestos fibers as safe. The long latency period (10 to 40 years) and high fatality rate of asbestos related diseases have led to regulations which apply to public and commercial buildings.

Section 2.0 - Sample Collection Procedures

Samples were collected and places into individual "Ziploc" bags and were clearly labeled with a unique identifier that corresponded to the analytical labs Chain of Custody (COC). PLM samples were then delivered to SEEML Labs located in Greenville, South Carolina while the TEM samples were overnighted to Eurofins Laboratories in Fort Mill, South Carolina. SEEML and Eurofins are asbestos accredited laboratories under the National Voluntary Laboratory Accreditation Program (NVLAP).

The building inspector has conducted the survey and sampling protocol using the Asbestos Hazard Emergency Response Act (AHERA) methodology.

Activities conducted by the building inspector consist of the following:

- A walkover of the property including all accessible areas.
- Identification of homogeneous areas of suspect asbestos materials.
- Assessment of the physical condition and potential for disturbance of suspect materials
- Collection of bulk samples from suspect materials
- Provide recommendations for the removal of present ACMs.

Every attempt has been made to sample all suspect ACM's in and on the structure. However, if a suspect material that has not been previously analyzed is encountered during the demolition activities, the suspect ACM should be sampled prior to disturbance.

Section 3.0 - Laboratory Analysis Methods

Nineteen (15 PLM, 4 TEM) samples were collected from the building and submitted to SEEML Labs in Greenville, South Carolina and Eurofins in Fort Mill, South Carolina. SEEML is accredited for bulk asbestos analysis by the National Institute of Standards and Technology (NIST) under NVLAP lab code 201031-0 and Eurofins is accredited for bulk asbestos analysis by the National Institute of Standards and Technology (NIST) under NVLAP lab code 600323-0. All suspect materials were analyzed using PLM methodology using the EPA Method 600/R93/116 and 600/M4-82/020 for analysis of asbestos in building materials and TEM methodology using the EPA Method 600/R-93/116 Sec 2.5.5.1.

Per SCDES regulation R.61-86.1, the definition of ACM is "material containing asbestos of any type either alone or mixed in with other materials, in an amount greater than one percent (1%) as determined by using the method specified in 40 CFR 763, Appendix A, Subpart F, Section 1 as amended or an acceptable equivalent." Please see Appendix B for copies of the analytical results provided to Upstate by SEEML and Eurofins labs.

Section 4.0 - State Asbestos Regulations

SCDES regulation 61-86.1 "Standards of Performance for Asbestos Projects" is more specific than the federal regulation, National Emission Standards for Hazardous Air Pollutants (NESHAP). Two of the most notable differences are that notification is required for any ACM prior to renovation or demolition (no limits) and a strict licensing program for all areas of inspection and abatement. In addition, the abatement air monitoring requirements are generally more stringent for SCDES.

SCDES must be notified in writing at least 10 days prior to a friable asbestos stripping or removal operation (removal in a commercial or public structure) that is greater than or equal to 260 linear feet on pipes, 160 square feet on other facility components, or 35 cubic feet of facility components where the area or length could not be measured prior to abatement. A 4-day notification to SCDES is required for a nonfriable abatement that is greater than or equal to 260 linear feet on pipes, 160 square feet on other facility components, or 35 cubic feet of facility components where the area or length could not be measured prior to abatement. Any quantity of ACMs (friable or nonfriable) requires permitting through SCDES prior to removal and the asbestos-containing waste must be disposed of at a landfill(s) licensed by SCDES to accept these materials. SCDES must also be notified in writing at least 10 days prior to demolition of a structure.

Section 5.0 - Building Description

The intent of this survey was to determine the presence and general locations of asbestos containing building materials that will be disturbed during demolition of the structure.

The following building components were observed.

- 1. Structural: Wood framing and beadboard.
- 2. Mechanical: Window units for air conditioning
- 3. Interior/Exterior Finishes: Drywall and joint compound covers beadboard wall covering. Floor coverings also include rubber, vinyl, and carpet flooring. Exterior of the structure is cementitious siding. Typical roofing shingles and felt make up roof layers.

Suspect Materials Observed in Scope of Survey Non-friable suspect ACM

Cementitious siding
Floor covering
Roofing materials
Hard window glazing

Friable suspect ACM

Drywall and joint compound

The scope of this survey/inspection is to identify materials that will be disturbed during demolition. If any unsampled suspect material is exposed during renovation, work should stop until proper sampling can be done.

The residential structure is generally in poor condition due to fire damage. The residential structure is estimated to be at least 60 years old.

Section 6.0 – Summary of Results

The scope of the comprehensive asbestos survey included the residential structure located at 113 League Street in Easley, South Carolina. The structure is to be demolished, therefore an asbestos survey by an SCDES-licensed Building Inspector is required (prior to demolition) to determine the presence and friability of ACMs to comply with the requirements of South Carolina regulation R.61-86.1 and 40 CFR Part 61 (National Emission Standards for Hazardous Air Pollutants - "NESHAP") as administered by the SCDES.

The analytical results indicate **the following** sampled suspect asbestos materials sampled tested **POSTIVE** for asbestos containing over 1%.

Homogeneous area "A"- Exterior cementitious siding. 15% Chrysotile. Approximately 3500 Square Feet Homogeneous area "B"- Drywall and joint compound throughout. 2-3% Chrysotile. Approximately 4550 Square Feet

The number and location of samples collected during this inspection was based on the type of material, the manner of application, and the homogeneity of the suspect ACM (similarity of color, texture, and type). The table below is provided to show which group bulk samples were collected by Upstate and to indicate the results of PLM and TEM analysis conducted by Eurofins Laboratories. Photos from the area are provided to depict the approximate amounts of the suspect asbestos-containing materials (ACMs). A total of five suspect (homogeneous) ACMs were observed.



UPSTATE ENVIRONMENTAL

Table 1 Asbestos Results Summary 113 League Street Easley, South Carolina

Sample Number	Sample Description and type (TSI, Miscellaneous, Surfacing)	Location	Analytical Results	Friable / Non- Friable	Current Condition	Potential for Disturbance	Estimated Quantity
A01-A03	Cementitious siding Miscellaneous material	Exterior	15% Chrysotile	Non-friable	Damaged	HPD	3500 SF
B01-B07	Drywall and joint compound Surfacing material	Throughout	2-3% Chrysotile	Friable	Significantly Damaged	HPD	4550 SF
C01-C03	12" x 12" Floor tile Miscellaneous material	Kitchen and small room	NAD	Non-friable	Damaged	HPD	150 SF
D01-D03	Roofing layers Miscellaneous materials	Roof	NAD	Non-friable	Good	HPD	2500 SF
E01-E03	Window glazing Miscellaneous material	Exterior windows	NAD	Friable	Damaged	HPD	250 LF
NOTES:	Quantities listed above are estimat Samples shown in bold are designate.		•				

3) Sampled by Johnny Satterfield, SCDES License Number BI-01674.

NAD - No Asbestos Detected

SF - square feet

Samples analyzed by PLM Microscopy and NOBS analyzed by TEM Microscopy.

PACM - Presumed Asbestos Containing Material

LF - linear feet

CF - cubic feet

LPD/HPD- Low/High potential for disturbance on renovation/demolition

Section 7.0 – Conclusion and Recommendation

On August 27, 2025, Johnny Satterfield of Upstate conducted a comprehensive asbestos survey of the residential structure located at 113 League Street in Easley, South Carolina. The area surveyed is limited to approximately 1600 square feet of fire damaged structure. Nineteen (19) samples were collected during this survey represent five (5) suspect ACMs.

Every attempt has been made to sample all the suspect ACMs in/on the building that are in the work area scope. However, if suspect material that has not been analyzed previously is encountered during demolition activities, the suspect ACM should be sampled prior to disturbance. The area of asbestos containing material shall be abated before any work being performed that could cause disturbance. This abatement should be performed by persons licensed by South Carolina Department of Environmental Services (SCDES).


Appendix A – Photographs of Suspect Materials



Homogeneous Area "A": Cementitious siding



Homogeneous Area "C": 12" x 12" Floor tile



2 Homogeneous Area "B": Drywall and joint compound



Homogeneous Area "D": Roofing layers





3

Asbestos Assessment 113 League Street Easley, South Carolina

Taken by: Johnny Satterfield

Date Taken: 8-27-25







Asbestos Assessment 113 League Street **Easley, South Carolina**

Taken by: Johnny Satterfield

Date Taken: 8-27-25

Appendix B – Laboratory Analysis

SEEML Reference Number: G-250828107

Date Issued: 08/28/2025



Southeast Environmental Microbiology Laboratories

102 Edinburgh Court Greenville, SC 29607 Phone: (864) 233-3770 Fax: (864) 233-6589

Asbestos Analytical Report By: Polarized Light Microscopy

This report has been prepared for **Upstate Environmental Consultants** the information and data has been checked for thoroughness and accuracy. The results reported apply only to the materials as received. The documents(s) contained herein are confidential and privileged information intended for the exclusive use of the individual or entity named above. This report shall not be reproduced except in full without SEEML's approval.

Client Project Name: 113	League Street
EPA 600/R-93/11	s prepared using this test method(s) contained within this document 6- Method for the Determination of Asbestos in Bulk Building Materials 40 CFR bpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk es
PLM 400 Point Co	ount (<0.25%) EPA 600/R-93/116
PLM 1000 Point C	Count (<0.1%) EPA 600/R-93/116
PLM Carb 435 Le	vel A Reporting Limit (<0.25%)
PLM Carb 435 Le	vel B (Reporting limit <0.1%)
PLM by EPA/600/	/R-93/116 with Milling Prep 400 Point Count
PLM Vermiculite	Initial Screening EPA 600R-93/116
PLM Cincinnati M	lethod 600/R-04/004 (Amphibole Only)
PLM Vermiculite	Method SOF-V 198.8 (Step 1 Chrysotile & Prep)
PLM Vermiculite	Method SOF-V 198.8 (Step 2 (Amphibole)

Approved By: Andrea Berrios Guden Ber

Thank you for choosing SEEML Labs. We strive to provide superior quality testing, analytical data and customer service. SEEML is accredited through the National Institute of Standards and Technology (NIST) National Voluntary Accreditation Program (NVLAP) for bulk asbestos analysis NVLAP # 201031-0 and licensed by the Texas Department of State Health Services (License Number: 300474). This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the US government.



Southeast Environmental Microbiology Laboratories - Asbestos Division

102 Edinburgh Court Greenville, SC 29607

Phone: 864-233-3770, Fax: 864-233-6589, www.seeml.com

NVLAP Lab ID:201031-0

PLM Asbestos Bulk Sample Summary

	Unatata Envira	D 1 C 1 1	00/00/0005			
		onmental Consultants			08/28/2025	
		oward Street		Date Received:		
	·	ourg, SC, 29303		Date Analyzed:		
	864	Date Reported:	08/28/2025			
		Date Revised:				
		Project Name:	113 League Street			
				Project No:		
Analyzed by:		Andre	a Rorrios	Project Address:	113 League Street	
Analyzed by: Andrea Berrios				City, State. ZIP:	easley, SC 29640	
Method:		Materials 40 CFR Appendix E to S	Determination of Asbestos in Bulk Building ubpart E of Part 763, Interim Method of the tos in Bulk Insulation Samples	SEEML Ref#:	G-250828107	
Client No.: Lab No:	Descri	Description/Location % Asbestos Type		% Fibrous Non- Asbestos Material Type	% Non-Fibrous Material	
A01 G-250828107-417A	(Gray) Siding/N/A		15% Chrysotile	None Detected	85% Carbon/Quartz	
A02 G-250828107-418A	(Gra	ray) Siding/N/A 15% Chrysotile		None Detected	85% Carbon/Quartz	
B01 G-250828107-419A		Joint Compound with een Paint/N/A	2% Chrysotile	None Detected	98% Binder/Filler	
B01 G-250828107-419B		Joint Compound-2nd Layer/N/A	2% Chrysotile	None Detected	98% Binder/Filler	
B01 G-250828107-419C	(Whi	te) Drywall/N/A	None Detected	15% Cellulose	85% Gypsum	
B02 G-250828107-420A	Charact Debat (N)		3% Chrysotile	None Detected	97% Binder/Filler	
B02 G-250828107-420B	(Whi	(White) Drywall/N/A None Detected		10% Cellulose	90% Gypsum	
B03 G-250828107-421A	(Off-White) Joint Compound with Green Paint/N/A 2% Chrysotile		2% Chrysotile	None Detected	98% Binder/Filler	
B03 (White) Drywall/N/A None Det		te) Drywall/N/A	None Detected	10% Cellulose	90% Gypsum	



The results in this report only apply to the samples as received.

NOB samples are tested as a preliminary analysis. We highly recommend for Negative NOB samples resulting in less than 1% Asbestos to be verified by TEM or Point Analysis.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. NAD means no asbestos fibers were detected. When detected the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Guidelines for Interpretation:

Any opinions/interpretations expressed in this report are outside the scope of this laboratory's accreditation. Interpretation of the data and information within this document is left to the company, consultant, and/or persons who conducted the fieldwork. A material is considered regulated asbestos containing material (ACM) where the asbestos content is determined to be one percent or greater. Several organizations, including the American Conference of Government Industrial Hygienists (ACGIH); the American Industrial Hygiene Association (AIHA); the Indoor Air Quality Association (IAQA); the United States Environmental Protection Agency (USEPA); the Centers for Disease Control (CDC) as well as the California Department of Health Services (CADHS) have published guidelines for assessment and interpretation of analytical data indicating a tested material is ACM.

Form 8.0 Rev. 8 04/29/20



Southeast Environmental Microbiology Laboratories - Asbestos Division

102 Edinburgh Court Greenville, SC 29607

Phone: 864-233-3770, Fax: 864-233-6589, www.seeml.com

NVLAP Lab ID:201031-0

PLM Asbestos Bulk Sample Summary

	Upstate Enviro	Date Sampled:	08/28/2025				
	1084 H	oward Street		Date Received:			
	Spartant	ourg, SC, 29303		Date Analyzed:	08/28/2025		
	864	Date Reported:	08/28/2025				
		Date Revised:					
				Project Name:	113 League Street		
				Project No:			
Analyzed by:		Andro	a Berrios	Project Address:	113 League Street		
Ariaryzed by.		Andre	a berrios	City, State. ZIP:	easley, SC 29640		
Method:		Materials 40 CFR Appendix E to Sul	tetermination of Asbestos in Bulk Building bpart E of Part 763, Interim Method of the os in Bulk Insulation Samples	SEEML Ref#:	G-250828107		
Client No.: Lab No:	Descri	Description/Location % Asbestos Type		% Fibrous Non- Asbestos Material Type	% Non-Fibrous Material		
B04 G-250828107-422A	(Tarry Solint Compound With On-Win		3% Chrysotile	None Detected	97% Binder/Filler		
B04 G-250828107-422B	(White) Drywall/N/A None De		None Detected	15% Cellulose	se 85% Gypsum		
B05 G-250828107-423A	(Tan) Joint Co	ompound with Off-White Paint/N/A	3% Chrysotile	None Detected	97% Binder/Filler		
B05 G-250828107-423B	(Whi	te) Drywall/N/A	None Detected	10% Cellulose	90% Gypsum		
B06 G-250828107-424A	(Tan) Joint C	Compound with Charred Paint/N/A	3% Chrysotile	None Detected	97% Binder/Filler		
B06 G-250828107-424B	(Tan) Joint Compound-2nd Layer/N/A		3% Chrysotile	None Detected	97% Binder/Filler		
B06 G-250828107-424C	(White) Drywall/N/A None Detected		None Detected	10% Cellulose	90% Gypsum		
B07 G-250828107-425A	(Tan) Joint C	Compound with Charred Paint/N/A	3% Chrysotile	None Detected	97% Binder/Filler		
B07 G-250828107-425B (Tan) Joint Compound-2nd Layer/N/A		3% Chrysotile	None Detected	97% Binder/Filler			



Disclaimer

The results in this report only apply to the samples as received.

NOB samples are tested as a preliminary analysis. We highly recommend for Negative NOB samples resulting in less than 1% Asbestos to be verified by TEM or Point Analysis.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. NAD means no asbestos fibers were detected. When detected the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Guidelines for Interpretation:

Any opinions/interpretations expressed in this report are outside the scope of this laboratory's accreditation. Interpretation of the data and information within this document is left to the company, consultant, and/or persons who conducted the fieldwork. A material is considered regulated asbestos containing material (ACM) where the asbestos content is determined to be one percent or greater. Several organizations, including the American Conference of Government Industrial Hygienists (ACGIH); the American Industrial Hygiene Association (AIHA); the Indoor Air Quality Association (IAQA); the United States Environmental Protection Agency (USEPA); the Centers for Disease Control (CDC) as well as the California Department of Health Services (CADHS) have published guidelines for assessment and interpretation of analytical data indicating a tested material is ACM.

Form 8.0 Rev. 8 04/29/20



Southeast Environmental Microbiology Laboratories - Asbestos Division

102 Edinburgh Court Greenville, SC 29607

Phone: 864-233-3770, Fax: 864-233-6589, www.seeml.com

NVLAP Lab ID:201031-0

PLM Asbestos Bulk Sample Summary

	United Fords		00/00/0005			
	•	onmental Consultants		Date Sampled:		
		oward Street			08/28/2025	
	·	ourg, SC, 29303		Date Analyzed:		
	864	-559-9559		· '	08/28/2025	
		Date Revised:				
				Project Name:	113 League Street	
				Project No:		
Analyzed by:		Andr	ea Berrios	Project Address:	113 League Street	
Attalyzed by.			City, State. ZIP:	easley, SC 29640		
Method:		Materials 40 CFR Appendix E to :	Determination of Asbestos in Bulk Building Subpart E of Part 763, Interim Method of the stos in Bulk Insulation Samples	SEEML Ref#:	G-250828107	
Client No.: Lab No:	Descri	Description/Location % Asbestos Type		% Fibrous Non- Asbestos Material Type	% Non-Fibrous Materia	
B07 G-250828107-425C	(White) Drywall/N/A None Detected		None Detected	15% Cellulose	85% Gypsum	
CO1 G-250828107-426A	(Cream) Floor Tile/N/A None Detected		None Detected	None Detected	100% Organic Matrix	
CO2 G-250828107-427A	(Crear	m) Floor Tile/N/A	None Detected	None Detected	100% Organic Matrix	
D01 G-250828107-428A	(Blac	ck) Shingle/N/A	None Detected	30% Fiberglass	70% Organic Matrix	
D01 G-250828107-428B	(Black	x) Tar Paper/N/A	None Detected	85% Cellulose	15% Organic Matrix	
D02 G-250828107-429A	(Black) Shingle/N/A None I		None Detected	30% Fiberglass	70% Organic Matrix	
D02 G-250828107-429B	(Black) Tar Paper/N/A None Detected		85% Cellulose	15% Organic Matrix		
E01 G-250828107-430A	(White) Window Glazing/N/A None Detected		None Detected	None Detected	100% Organic Matrix	
E02 G-250828107-431A	(White) V	E02 (White) Window Glazing/N/A None Detected		None Detected	100% Organic Matrix	

Approved By: Andrea Berrios (under Bu-



Disclaimer

The results in this report only apply to the samples as received.

NOB samples are tested as a preliminary analysis. We highly recommend for Negative NOB samples resulting in less than 1% Asbestos to be verified by TEM or Point Analysis.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. NAD means no asbestos fibers were detected. When detected the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Guidelines for Interpretation:

Any opinions/interpretations expressed in this report are outside the scope of this laboratory's accreditation. Interpretation of the data and information within this document is left to the company, consultant, and/or persons who conducted the fieldwork. A material is considered regulated asbestos containing material (ACM) where the asbestos content is determined to be one percent or greater. Several organizations, including the American Conference of Government Industrial Hygienists (ACGIH); the American Industrial Hygiene Association (AIHA); the Indoor Air Quality Association (IAQA); the United States Environmental Protection Agency (USEPA); the Centers for Disease Control (CDC) as well as the California Department of Health Services (CADHS) have published guidelines for assessment and interpretation of analytical data indicating a tested material is ACM.

Form 8.0 Rev. 8 04/29/20

September 05, 2025

Johnny Satterfield Upstate Environmental, Llc 194 Evans Rd Easley, SC 29640-7978

CLIENT PROJECT: 113 League Street

LAB CODE: 686970-1

Dear Johnny,

Enclosed are asbestos analysis results for TEM bulk samples received at our laboratory on September 3, 2025. The samples were analyzed for asbestos using transmission electron microscopy (TEM) per Chatfield/EPA 600/R-93/116 Sec. 2.5.5.1 method.

Sample results containing > 1% asbestos are considered asbestos-containing materials (ACMs) per the EPA regulatory requirements. The detection limit for the TEM Chatfield/EPA 600/R-93/116 Sec. 2.5.5.1 method is <1% depending on the processed weight and constituents of the sample.

Thank you for your business and we look forward to continuing good relations.

Kind Regards,

Tianbao Bai, Ph.D., CIH Laboratory Director

NVLAP 600323-0



ASBESTOS ANALYTICAL REPORT By: Transmission Electron Microscopy

Prepared for

Upstate Environmental, Llc

CLIENT PROJECT: 113 League Street

LAB CODE: 686970-1

TEST METHOD: Bulk Chatfield EPA 600 / R93 / 116 Sec. 2.5.5.1

REPORT DATE: 09/05/25



ASBESTOS BULK ANALYSIS

By: Transmission Electron Microscopy

Client: Upstate Environmental, Llc Lab Code: 686970-1

194 Evans Rd

Date Received: 09/03/25 Easley, SC 29640-7978 **Date Analyzed:** 09/05/25

Date Reported: 09/05/25

Project: 113 League Street

Method: TEM BULK CHATFIELD / EPA 600 / R93 / 116 Sec. 2.5.5.1

Client ID Lab ID	Material Description	Sample Weight (g)	Organic Material (%)	Acid Soluble Material (%)	Acid Insoluble Material (%)	ASBESTOS %
C03 3686570	Brown/tan floor tile	0.22	15.9	79.49	4.61	None Detected
D03 3686571 Layer A	Gray/black roofing	0.21	25.89	47.23	26.88	None Detected
Layer B	Black felt paper	0.28	93.31	0.81	5.88	None Detected
Layer C	Black roofing	0.34	20.07	53.89	26.04	None Detected
E03 3686572	White glazing	0.16	29.94	63.34	6.72	None Detected



LEGEND: None

METHOD: Bulk Chatfield EPA 600 / R93 / 116 Sec. 2.5.5.1

LIMIT OF DETECTION: Varies with the weight and constituents of the sample (<1%)

REGULATORY LIMIT: 1%

Eurofins Built Environment Testing East, LLC makes no warranty representation regarding the accuracy of client submitted information in preparing and presenting analytical results. Interpretation of the analytical results is the sole responsibility of the client. This report relates only to the samples tested or analyzed and may not be reproduced, except in full, without written approval by Eurofins Built Environment Testing East, LLC.. Estimated measurement of uncertainty is available on request. Samples were received in acceptable condition unless otherwise noted.

Information provided by customer includes customer sample ID, location, volume and area as well as date and time of sampling. Eurofins Built Environment Testing East, LLC recommends between 0.500 and 0.200 grams of sample material. Any weight below 0.100 grams is considered below protocol guidelines.

Hannah Mills Analyst

DATA QA:

Raegan Brown 9/5/2025

APPROVED BY:

Tianbao Bai, Ph.D., CIH Laboratory Director



Built Environment Testing

RES Job #: 686970

SUBMITTED BY	INVOICE TO	CONTACT INFORMATION	SERIES
Company: Upstate Environmental, Llc	Company: Upstate Environmental, Llc	Contact: Johnny Satterfield	-1 TEM Priority 48
Address: 194 Evans Rd	Address: 194 Evans Rd	Phone: (864) 884-4284	
		Fax:	
Easley, SC 29640-7978	Easley, SC 29640-7978	Cell: (864) 884-4284	
Project Number and/or P.O. #: 113 League Street	Project Zip Code:	Final Data Deliverable Email Address:	
Project Description/Location: 113 League Street		johnny@upstateenvironmental.com	

ASBESTOS LABORATORY	,					REC	QUESTED) AI	NALYSIS					V	ALID	MAT	RIX C	ODE	S		LAB NOTES
PLM / PCM / TEM	DTL RUSH PRIORITY STANDARD													Air	r = A			Bu	lk = B		
														Dus	st = D		<u><u>l</u></u>	Foo	od = F	:	
CHEMISTRY LABORATOR	Υ													Pair	nt = P			So	il = S		
Dust	RUSH PRIORITY STANDARD													Surfac	ce = S	U		Swa	b = S\	Ν	
Metals	RUSH PRIORITY STANDARD *PRIOR NOTICE REQUIRED FOR SAME DAY TAT			hatfield")										Тар		king W	/ater =	DW	e = W	/	
Organics*	SAME DAY RUSH PRIORITY STANDARD			116 - "C									**AS	TM E	Was 1792 :		ater = \ ved wi		edia o	nly**	
MICROBIOLOGY LABORA	TORY			۲-93-											_	:					
Viable Analysis** Medical Device Analysis	PRIORITY STANDARD **TAT DEPENDENT ON SPEED OF MICROBIAL GROWTH RUSH STANDARD			ve (EPA-600-F											or Area/Aliquot)						
Mold Analysis	RUSH PRIORITY STANDARD			uantitat									'Area	(°C)	x Width(
	establish a laboratory priority, subject to laboratory volume and are not Additional fees apply for afterhours, weekends and holidays.**			Semi-Q			ΓS	ORGANICS	ES	CAL			lume (L)	mperatur	Aliquots);	ø.	i i	D	l/yy	Collected h:mm	
Special Instructions: SC samples, SC 2 day TEI	M, *Please see COC*	PLM		TEM.	PCM	DUST	META	ORG,	VIABLES	MEDIC/	MOLD		mple Vol	Sample Tempe	Length(or/	Matrix Code	0	Containers	Date Collected mm/dd/yy	ime Coll hh:m	Laboratory Analysis Instructions
Client Sample ID Number	(Sample ID's must be unique)	Α	ASBE	ESTO	os	СН	EMISTRY	1	MICROBI	OLO	GΥ	ICO	Sa	Sal	Le	™a	‡) (‡	ר	-	
1 C03		1		X												В		Ī			
2 D03		<u> </u>		X	I			[В			Ī	Ι	
3 E03				X												В					

Eurofins Built Environment Testing East, LLC establishes a unique Lab Sample ID, for each sample, by preceding each unique Client Sample ID with the laboratory RES Job Number.

Eurofins Built Environment Testing East, LLC will analyze incoming samples based on information received and will not be responsible for errors or omissions in calculations resulting from the inaccuracy of original data. By signing, client/company representative agrees that submission of the following samples for requested analysis as indicated on this Chain of Custody shall consitute an analytical services agreement with payment terms of NET 30 days. Failure to comply with payment terms may result in a 1.5% monthly interest surcharge.

Relinquished By:	Date/Time: 09/03/2025 9:31:06	Sample Condition: Acceptable

Received By: Candice Wilkins Date/Time: 09/03/2025 10:54:55 Carrier: Fed-Ex



CHAIN OF CUSTODY

CFI

730 SE Maynard Road, Cary, NC 27511 Tel: 866-481-1412; Fax: 919-481-1442

LAB USE ONLY:	08(0910-1
CEI Lab Code:	
CEI Lab I.D. Range:	建 型 对注意现代 2

COMPAN	Y INFORMATION	PROJECT INFORMATION					
CEI CLIEN	T#:	Job Contact; Johnny Satterfield					
Company: Upstate Environmental		Email / Tel: 864-884-4284					
Address:	194 Evans Road	Project Name: 113 League Street					
	Easley, SC 29640	Project ID#:					
Email:	johnny@upstateenvironmental.com	PO #:					
Tel: 864-88	4-4284 Fax:	STATE SAMPLES COLLECTED IN: South Carolina					

	TAT IS NOT MARKE	TURN AROUND TIME												
ASBESTOS	METHOD	4 HR	8 HR	1 DAY	2 DAY	3 DAY	5 DAY							
PLM BULK	EPA 600					DA	JUAT							
PLM POINT COUNT (400)	EPA 600													
PLM POINT COUNT (1000)	EPA 600													
PLM GRAV w POINT COUNT	EPA 600													
PLM BULK	CARB 435	HE BUILD			- Interesting									
PCM AIR	NIOSH 7400													
TEM AIR	EPA AHERA													
TEM AIR	NIOSH 7402		F	a										
TEM AIR (PCME)	ISO 10312		ā											
TEM AIR	ASTM 6281-15		Ser Transit		64 34 3 5									
TEM BULK	CHATFIELD		T											
TEM DUST WIPE	ASTM D6480-05 (2010)		in a				100							
TEM DUST MICROVAC	ASTM D5755-09 (2014)			H										
TEM SOIL	ASTM D7521-16													
TEM VERMICULITE	CINCINNATI METHOD			1000										
TEM QUALITTATIVE	IN-HOUSE METHOD	en in a			and the latest and th									
OTHER:		THE PERSON NAMED IN COLUMN 1												
Positive Stop So		y Taz	er hi	45	Olyvaco Reje	ept Sample								
Relinquished By	Date/Time		Receive	ed By:		ate/Time								
11 1/1/1						ucci i dile								
Am lotter	9/1/25 09	00	(.0	JUN 1	213/202	1								

Samples will be disposed of 30 days after analysis

Page __/ of _____ Version: CCOC.01.18.1/2.LD



SAMPLING FORM

CEI

COMPANY CONTACT INFORMATION				
Company: Upstate Environmental	Job Contact: Johnny Satterfield			
Project Name: 113 League Street, Easley, SC				
Project ID #:	Tel: 864-884-4284			
- 10ject 12 #.	Tel: 004-084-4284			

SAMPLE ID#	DESCRIPTION / LOCATION	VOLUME/ AREA		14 14 14 14 14 14 14 14 14 14 14 14 14 1
C03	12x12 Floor Tile	ANLA	PLM	The state of the s
D03	Roofing Materials		PLM	
	Window Glazing		PLM	
			PLM	
			PLM D	TEM
			PLM	TEM
			PLM	TEM
			1,000	TEM
			PLM	TEM 🗀
			PLM	TEM 🗀
			PLM	TEM
			PLM	TEM 🗀
			PLM	TEM
		-	PLM	
			I LIVI	TEM

Appendix C – Inspector Credentials

