

## PUBLIC WORKS DEPARTMENT

**TOWN OF WINCHESTER** 189 Rowley Street Winsted, CT 06098 Phone (860) 379-4101 Fax: (860) 738-3509

	Laurana ant David
2022 Road and Infrastructure Improvement Bond	
Road Segment Information Sheet	
Lake Street	
From Boyd St	To East and West Lake St
Improvement Scheduled	FY 2027
2019 Paser Rating	<b>Poor (3) to Fair (4)</b>
Estimated Cost/Town Share: \$1,643,000	\$643,000
Description of Existing Conditions Pavement - Lake Street has a map cracked surface. Settlement has occurred in areas of past utility excavations. Drainage	WEST
Drainage   Surface flow – The slope of the road   prevents significant ponding. The crown is less   than needed to keep gutter flow at the edges of   the road.   Inlets - The catch basin inlets are old cast   iron and have corroded metal and masonry   supports. Additional basins are needed to   reduce gutter flow   Pipes - The condition of the pipes is not   known. Due to their age, they should be   replaced.   Sidewalks - The Sidewalks from Boyd St to   East Lake St are in poor condition. There are   no handicapped access ramps.	The second sec

Buried Utilities	
Water – The water lines are in good	
condition and there are no plans for work on	
these pipes.	
Sewer – The sewer pipes are old clay pipe	
and require improvement; however, they can be	
repaired using trenchless methods.	
Eversource Gas – Eversource gas has work	
planned in 2022	
Other – All other utilities appear to be	
overhead.	
Other Concerns – There is a long history of	
accidents at or near the Rockwell St intersection	
and the curve just to the north. Road	
realignment is needed to reduce the conditions	
that result in these accidents. The pavement is	
excessively wide from Rockwell to East Lake	
St. On Street parking in this area should be	
discouraged.	
uiscourageu.	
This is an important street for Access to the	
Highland Lake Area.	
	Photo 2. Looking North to Curve
Proposed Improvements	
Description of Work	NY X
1. Eversource will replace the Gas Lines	
2. The curve alignment will be improved.	
3. The Rockwell St intersection will be	
improved.	
4. The pipes and all catch basins will be	- A Charles and the second sec
replaced or added as needed.	
<ul><li>replaced or added as needed.</li><li>5. There will be a total reconstruction of the</li></ul>	
<ul><li>replaced or added as needed.</li><li>5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake</li></ul>	
<ul><li>replaced or added as needed.</li><li>5. There will be a total reconstruction of the</li></ul>	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St.	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been made to LOTCIP program.	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been made to LOTCIP program. Budget for Improvements: \$1,643,000	
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been made to LOTCIP program. Budget for Improvements: \$1,643,000 LOTCIP Participation - \$1,000,000 (estimated)	Photo 3. Looking from Boyd up Lake St
replaced or added as needed. 5. There will be a total reconstruction of the Road and Sidewalks from Boyd St to East Lake St. Status of Design – An Application has been made to LOTCIP program. Budget for Improvements: \$1,643,000	Photo 3. Looking from Boyd up Lake St