

PUBLIC WORKS DEPARTMENT

TOWN OF WINCHESTER

189 Rowley Street Winsted, CT 06098 Phone (860) 379-4101 Fax: (860) 738-3509

2022 Road and Infrastructure Improvement Bond						
Road Segment Information Sheet						
Oakdale Ave						
From	From Old New Hartford Rd		To	Pump Station		
Improvement Scheduled			FY 202	FY 2024		
2019 Paser Rating			Fair (4) to Good (5)		
Estimated Cost/Town		\$750,000				
Share:						

Description of Existing Conditions

Pavement – The surface is map cracked. Sink holes appear on a regular basis creating the need for frequent patching to eliminate hazardous conditions.

Drainage

Surface flow – slope on Roadway keeps water from ponding. The curb reveal low which limits the capacity of flow in the gutters.

Inlets – The catch basin inlet are in fair condition.

Pipes – The pipes are in poor condition. They show erosion and corrosion in the inverts allowing soil to enter the pipe creating the sink holes seen in the surface of the road.

Sidewalks – There are no sidewalks.



Photo 1.

Water – The water is in good condition. Sewer – The sewer pipe is in poor condition. Eversource Gas – Gas Main are not scheduled for replacement. Other – Other Considerations – This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Buried Utilities	
Sewer – The sewer pipe is in poor condition. Eversource Gas – Gas Main are not scheduled for replacement. Other – Other Considerations – This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spor Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Eversource Gas – Gas Main are not scheduled for replacement. Other – Other – Other Considerations – This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	_	
scheduled for replacement. Other — Other Considerations — This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design — Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Other — Other Considerations — This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design — Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Other Considerations – This road is an important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	_	
important access to student drop off at Regional 7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
7 School and to access the Cellular Tower serving the Town. Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Sink Holes cause a hazard to travelling public forecasting collapse of the drainage pipes. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	serving the Town.	
Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Sink Holes cause a hazard to travelling	
Photo 2. Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design — Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	pipes.	
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
Proposed Improvements Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		Dhata 1
Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		P110t0 2.
1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Due a see d Incompany of the	
pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000		
2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work	
3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a	Photo 3.
3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system.	Photo 3.
pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system.	Photo 3.
recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal.	Photo 3.
3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal.	Photo 3.
Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the	Photo 3.
Status of Design – Final design is ready to begin. Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and	Photo 3.
Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials.	Photo 3.
Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled	Photo 3.
Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled	Photo 3.
Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled	Photo 3.
Budget for Improvements Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled	Photo 3.
Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface.	Photo 3.
Preliminary Cost Project Est - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to	Photo 3.
	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin.	Photo 3.
	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin.	Photo 3.
Total Town Shore Estimate \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements	Photo 3.
Total Town Chara Estimate \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements	Photo 3.
Total Town Share Estimate - \$750,000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements	Photo 3.
10tal 10wii Shafe Esumate - 5/50.000	Description of Work 1. The drainage system will be repaired with a pipe lining system. 2. The road will have a deep mill to regain curb reveal. 3. Spot Repairs will be made over the top of the pipe by removing the pavement and recompacting the soil and base materials. 3. 2" of asphalt will be added to the milled surface. Status of Design – Final design is ready to begin. Budget for Improvements	Photo 3.