




PUBLIC WORKS DEPARTMENT

TOWN OF WINCHESTER

189 Rowley Street

Winsted, CT 06098

Phone (860) 379-4101 Fax: (860) 738-3509

2022 Road and Infrastructure Improvement Bond				
Road Segment Information Sheet				
South Rd				
From	Winchester Rd		To	Hollow Road
Improvement Scheduled			FY 2024	
2019 Paser Rating			Very Poor (2) to Poor (3)	
Estimated Cost/Town Share		\$550,000	\$550,000	
Description of Existing Conditions				
Pavement – The surface is map cracked. Recent skim coat along a short section near Newfield Rd has improved the ride; however, this treatment was a temporary fix. Weak base causes tire rutting.				
Drainage				
Surface flow – is generally adequate; however, the crown in the road is lower than desired to contain the drainage to the shoulders. This situation causes significant icing in the winter.				
Shoulders – are generally above the pavement which tends to trap the water on the pavement accelerating edge cracking. One section along the road has a deep drainage trench which is a hazard.				
Inlets – There are limited catch basins on this section.				
Pipes – Cross culvert are the typical method of Pavement drainage. The pipes are in poor condition.				
Sidewalks – There are no sidewalks on this rural road.				
			Photo 1.	

Town of Winchester
Public Works Department