

PUBLIC WORKS DEPARTMENT

TOWN OF WINCHESTER

189 Rowley Street Winsted, CT 06098 Phone (860) 379-4101 Fax: (860) 738-3509

2022 Road and Infrastructure Improvement Bond		
Road Segment Information Sheet		
Holabird Avenue		
From		То
Whiting St		Florence Ave
Improvement Scheduled		FY 2023
2019 Paser Rating		Very poor (2) to Poor (3) Temporary Repairs were made to improve conditions in 2020
Estimated Cost/Town Share:	\$2,763,600	\$1,523,600
Description of Existing Conditions		
Pavement – A map and alligator cracked surface.		Photo 1. Interior Pipe View
Frequent severe potholes form across the road.		
D :		
Drainage Surface flow the steerness of the read been		
Surface flow – the steepness of the road keep the water moving but significant flow by-passes		
inlet grates causing heavy gutter flow and icing in		
winter.		
Inlets - The catch basin inlets are old cast iron		
and have corroded metal and masonry supports.		
Pipes - The main trunk line is a mixture of		
metal and concrete. The metal portions have		9
corroded to the point where the inverts are heavily		⊢ ·· ≥
corroded. Sink holes are forming along the length		9 - 9
of the pipes which require frequent repair along the		S D B D E C
lower sections.		E E E E E E E E E E E E E E E E E E E
Sidewalks - The Sidewalks will be replaced in		3 F T S
kind from Whiting St to Colony Ave.		0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1 0 1
,		3.4 3.7 3.7 3.0 1.1 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0 3.0
		Q Q 0 1 4 V

Buried Utilities

Water – The water lines are old cast iron pipes and are scheduled for replacement in FY 2022.

Sewer – The sewer pipes are old clay pipe and require improvement; however, they can be repaired using trenchless methods.

Eversource Gas – Eversource gas has no planned improvements.

Other – None

Other Considerations – There is road work planned in the neighborhood on Whiting St and continues the work done on Holabird Bridge



Photo 2. Looking past Colony to Gilbert

Proposed Improvements

Description of Work

- 1. Water and Sewer Commission will Replace Water Mains.
- 2. The pipes and all catch basins will be replaced or added as needed.
- 3. There will be a total reconstruction of the Road from Whiting St to Florence Ave.
- 4. The existing sidewalks on both sides will be replaced

Status of Design – The consulting Engineers are in the process of completing the design.

Budget for Improvements

Per Engineer's Estimate Whiting to Colony \$1,430,000

Colony to Florence - \$1,333,600

LOTCIP Grant (\$1,200,000) Whiting to Colony

Utility Participation – (\$40,000) Approx.

Total Estimated Town Share - \$1,523,600



Photo 3. Looking - Colony to Florence