



## PUBLIC WORKS DEPARTMENT

### TOWN OF WINCHESTER

189 Rowley Street


Winsted, CT 06098


Phone (860) 379-4101 Fax: (860) 738-3509

## 2022 Road and Infrastructure Improvement Bond

### Road Segment Information Sheet

### Indian Meadow Drive

From	Marshall St	To	Dead End
Improvement Scheduled		FY 2023	
2019 Paser Rating		Poor (3)	
Estimated Cost/Town Share:		\$106,000	\$106,000
Description of Existing Conditions			
Pavement – The surface is alligator and map cracked.			
Drainage			
Surface flow – Some ponding of surface water occurs along the shoulders due to poor crown and some settlement.			
Inlets – The few catch basins on the road are all in good condition or have been recently replaced.			
Pipes - The pipes are typically corrugated metal pipe. The pipe appears in good condition.			
Sidewalks – There are no sidewalks on this rural road.		Photo 1: At Marshall looking to the High Point	

<p><b>Buried Utilities</b></p> <p>Water – There are no water lines.</p> <p>Sewer – There are no sewer pipes.</p> <p>Eversource Gas – There is no gas in this Road.</p> <p>Other – Communication lines appear to be mounted on Utility Poles.</p> <p>Other Considerations – This work should be done with two other streets in the neighborhood: Marshall and Indian Meadow Rd to minimize mobilization costs.</p>	 <p><b>Photo 2. Looking West to Cul-de-Sac</b></p>
<p><b>Proposed Improvements</b></p> <p><b>Description of Work</b></p> <p>1. The project will be a full depth reclamation of the pavement surface with additional aggregate added and finished grade.</p> <p>2. 3” of pavement will be laid</p> <p><b>Status of Design –</b> The work will be done off of State Bid. No design required.</p> <p><b>Budget for Improvements</b></p> <p>Drainage - Several Catch Basins will have the inlet elevation adjusted.</p> <p>Reclaim and 3” of Pavement \$106,000</p> <p><b>Total Estimate Costs - \$106,000</b></p>	